

Eaton Corporation  
Innovation Center  
26201 Northwestern Highway  
P.O. Box 766  
Southfield, MI 48037  
248 / 354-2700

---



November 28, 2000

Ing. Hector Rios Salazar  
Distribuidora de Aceites Mexicanos ACEIMEX, S.A. de C.V.  
Norte 35 No. 983 Bodega 12  
Col. Industrial Vallejo  
C.P. 07729  
Mexico, D.F.

Dear Ing. Salazar:

Based on the test reports and supporting documents provided by Chevron Oronite Company LLC on 11/27/00, and my letter of 3/4/99, it is our opinion that Distribuidora de Aceites Mexicanos ACEIMEX HIDRO LUB ISO 32 meets the antiwear requirements for Mobile Hydraulic systems data sheet M-2950-S, and for Industrial Hydraulic Systems data sheet I-286-S.

It is noted that the polyacrylate foam inhibitor is now included in the OLOA 9740M. The inclusion of the foam inhibitor has increased the additive treat OLOA 9740M from 0.85 wt% to 0.86 wt%.

Sincerely,

A handwritten signature in black ink, appearing to read "Thelma Marougy". The signature is fluid and cursive, with a large loop at the end.

Thelma Marougy  
Principal Engineer  
Fluids Specialist

Cc: Gary Kassen  
Tom I. Lewis  
Mike Abraham  
Gale Maddy  
Mike Gust  
Kirk Garrett